(c) Matt Brettle 2001



Description	Interpretation
	turbiditic sandstone
black parallel laminated muds	
non erosive, sharp based silt	distal / off axis mouthbar
paper laminated black mudstone	
?No fauna observed, but memoirs mention R2a ammonoids	marine flooding surface



Description	Interpretation
	turbiditic sandstone
erosive relief, dip of surface 25/159	
abundant ammonoids (5cm band), orange weathered clay	marine flooding surface
black paper laminated mudstone, sulphurous	
	distal / off axis mouthbar
increased induration implies increase silt content, colour grey	
not exposed	